

Vente avion FALCON 900B

ANNEE DE CONSTRUCTION:
MOTEURS: (MSP GOLD)
APU:

1997
HONEYWELL TFE 731-5BR
HONEYWELL GTCP36-150

HEURES TOTALES:
ATTERRISSAGES:

3 766 HEURES
1 921 ATTERRISSAGES

CONFIGURATION INTERIEURE: CLUB 4 AVANT, DINING GROUP 4 CENTRAL, DIVAN ARRIERE
FAISANT FACE A UN SIEGE EXECUTIVE. TOILETTES AVANT ET ARRIERE.
SYSTEME DVD ET CD - AIRSHOW

AVIONIQUE: SYSTEME EFIS HONEYWELL EDZ-820 – A/P HONEYWELL SPZ-8000
EGPWS HONEYWELL MARK V – TCAS II COLLINS TTR-920 – HONEYWELL LASEREF
RVSM COMPLIANT – N1 DEEC – RNP10 – 8.33 & FM IMMUNITY – EFB CLASS 2 (DOUBLE)
CAMERA COCKPIT

CHECK 2C & REVISION GENERALE DES TRAINS 2009
INSPECTION 7 (CORROSION) 2012
PEINTURE REFAITE EN 2004

